

24" Front Load Washer


WMY10148C2



KEY FEATURES

- Compact washer
- 1400 rpm maximum spin speed
- Electronic Control
- 2.5 cu. ft. washer capacity
- Pet Hair Removal Plus

GENERAL	
Capacity cu. ft.	2.5
Style	Front loading
Maximum spin speed rpm	1400 rpm
Variable spin speed	Yes
Automatic temperature control	Yes
Control	Digital display
Delay time	0-24 hr
Remaining time indicator	Yes
Silence level (washing) dBA	52 dBA
Drum material	Stainless Steel
Dispenser	Yes
FUNCTIONS	
Heavy Soil	Yes
Pre Soak	Yes
Rinse Plus (Extra rinse)	Yes
Child Lock	Yes
Automatic water adjustment system	Yes
Unbalance detection system	Yes
Wash system with internal water heater	Yes
CYCLES	
Number of cycles	16
Cottons / Normal	Yes
Heavy Duty	Yes
Wrinkle free	Yes
Pet Hair Removal Plus	Yes
Delicates	Yes
Spin + Drain	Yes
Rinse	Yes
Super Quick 20 min	Yes
Bedding	Yes
Sportswear	Yes
FINISHES	
Cabinet	White
Door Rim	Chrome
Cycle Selector Knob	Chrome
TECHNICAL FEATURES	
Rated Current Amps	10 A
Voltage / Frequency	208-240 V / 60 Hz
Power Plug	Plugs into matching dryer
ENVIRONMENTAL STANDARDS	
Energy star qualified	Yes
Energy consumption kWh/year	86
DIMENSIONS	
Product Dimensions (H x W x D) in	33 ¹ / ₁₀ x 23 ³ / ₅ x 26 ³ / ₁₀ in.
Product Dimensions (H x W x D) cm	84 x 60 x 67 cm
Product Weight kg	76kg
Product Weight lbs.	167.5 lbs.



Required minimum air gap clearances :
 1/2" top, 1/2" sides, 1/2" back

NOTE TO THE INSTALLER: All height, width, and depth dimensions are shown in inches (as well as metric). Beko U.S., Inc. reserves the absolute and unrestricted right to change product materials and specifications, at any time, without notice. Please visit our website, www.BekoAppliances.com, or call 888.352.2356 to verify the latest specifications with final dimensional data and other details prior to installation and making a cutout. Applicable product limited warranty information may be found in accompanying product materials, or you may contact your account manager for further details. Proper installation is the responsibility of the installer. Product failure due to improper installation is not covered under the Limited Warranty.